



# CAL FIRE - OFFICE OF THE STATE FIRE MARSHAL

## Information Bulletin 24-002

Issued: March 21, 2024


### Honeywell Recalls System Sensor L-Series Low Frequency Fire Alarm Sounders and Strobes



Product label  
4-digit date code  
3034 and 3035



Carton label  
Individual product  
4-digit date code  
3034 and 3035



Carton label  
10 unit bulk pack  
'-BP10'  
4-digit date code  
3034 and 3035

On March 14, 2024, Honeywell and System Sensor recalled System Sensor L-series Low Frequency Sounders and Strobes for residential apartments and commercial buildings because the sounders and strobes can malfunction and cause the fire alarm system to fail to alert consumers of a fire.

The model number, date codes and "System Sensor" are printed on the product label and carton. Date codes 3034 and 3035 and the following models are included in this recall:

Models	CSFM Listing No.
HWL-LF, HWL-LF-BP10	7135-1653:516
HRL-LF, HRL-LF-BP10	7135-1653:516
HGWL-LF-BP10	7135-1653:516
P2WL-LF	7135-1653:517

Consumers should contact System Sensor to arrange for an inspection, repair, or replacement.



## CAL FIRE - OFFICE OF THE STATE FIRE MARSHAL Information Bulletin 24-002

---

Additional information on the recall from the US Consumer Product Safety Commission and Honeywell:

[Honeywell Recalls System Sensor L-Series Low Frequency Fire Alarm Sounders and Strobes Due to Risk of Failure to Alert Consumers to a Fire | CPSC.gov](#)

[Recall | System Sensor | Honeywell](#)

[SSR24.1SB - System Sensor Low Frequency Sounder Notice with DEALER Certificate of Compliance.pdf \(honeywell.com\)](#)